



Care

Maintenance

COMPAC
THE SURFACES COMPANY



COMPAC Technological Quartz needs only regular cleaning with a neutral pH product soap/detergent, rinse with water and dry with a dry microfiber cloth or absorbent paper towel.

To eliminate any remains or residues, (Eg. oil or fat, wine, vinegar, lemon, soft drinks, coffee, etc.) from the COMPAC TECHNOLOGICAL QUARTZ surface, just wipe with a damp cloth impregnate with neutral pH detergent, rinse with water and dry it.

- **Fat stains**: dilute a small amount of detergent in some water and rub over the stain using a cloth. Next, rinse it off with water.
- **Water lime marks**: pour some vinegar (or any other diluted weak acid such as hydrochloric acid) directly on the surface to be treated. Rinse it off with plenty of water.
- **Silicone stains**: Scrape off using a blade and use a little solvent for any remains left behind (ethanol).

BASIC TECHNICAL SPECIFICATION AND MAINTENANCE TIPS

- Do not fit COMPAC Technological Quartz outside or in places where UV ray lamps are fitted (in places subject to intense solar radiation or UV lamps).
- Do not place objects recently removed from heat on COMPAC Technological Quartz surfaces on a regular basis (frying pans, etc.).
- Do not use water repellents or sealers to enhance the shine.
- Do not use strippers, caustic soda, degreasers or products with pH in excess of 10 or chlorine based products. Do not use products that contain hydrofluoric acid or dichloromethane. If you use bleach or solvent, you must rinse it off using water and never leave it long-time in contact with the surface.
- COMPAC Technological Quartz should not be polished, either on flooring or work surfaces.
- Avoid external heat sources from the countertop.